Atty Docket No.: JCLA6224-R

Serial No.: 09/727,946

Please add new claim 17 as follows:

(Newly Added) The system of claim 1, wherein the inlet and the outlet of each

pipeline are on a same side or within a same quadrant of the hot plate.

Claims 2-7 remained as eyer.